



July 18, 2016

End of Life Notice:
MPS1000 WAN/LAN Communications Server
and
CPC358 Synchronous Serial Controller

This is formal notification that the MPS1000 WAN/LAN Communications Server and CPC358 Synchronous Serial Controller are being declared End of Life (EoL) due to obsolete parts. The MPS1000 WAN/LAN Communications Server will be replaced by the Ventnor Communications Server. The CPC358 Synchronous Serial Controller will not be replaced.

MPS1000 and CPC358 Part IDs

The following is a list of the specific Part IDs (Affected Product) being declared EoL.

Product	Description
PT-MPS1000-12035	16 Port WAN/1 LAN Communication Server / AC Power
PT-MPS1000-12159	8 Port WAN/1 LAN Communication Server / AC Power
PT-MPS1000-12386	4 Port WAN/1 LAN Communication Server / AC Power
PT-MPS1000-91457	Custom bundle with Radar+Tadil-B+HABM
PT-MPS1000-91530	Custom 16-port bundle with Tadil-B and Cables
PT-MPS1000-91531	Custom 8-port bundle with Tadil-B and Cables
PT-MPS1000-91675	MODEL PT-MPS1000-91675 4 PORT
PT-MPS1000-91776	MODEL PT-MPS1000-91776
PT-MPS1000-91797	MODEL PT-MPS1000-91797
PT-CPC358-11932	Eight Port Synchronous Serial Controller, Rear I/O
PT-RTM358-11934	CPC358 Rear Transition Module for all Rear I/O versions
PT-RTM358-12382	CPC358 4 Port Rear Transition Module for all Rear I/O versions
PT-ACC358-12275	RS232 Debug Cable (console)
PT-CPC358H-91295	Revision Locked CPC358 with HDLC RTU
PT-RTM358-91296	Revision Locked RTM358

Sunhillo Corporation
444 Kelley Drive
West Berlin, New Jersey 08091-9210 USA
www.sunhillo.com Tel: +1 856.767.7676

Lifecycle Dates

Sunhillo is providing guidance with respect to the Last Order Date (LOD), Last Ship Date (LSD) and End of Support (EoS) for Affected Product.

Last Order Date (LOD)

Orders will be accepted through **August 26, 2016**. Given there are limited product quantities available, Sunhillo reserves the right to limit customer order quantities.

Last Ship Date (LSD)

Orders placed before the LOD may be shipped through **March 31, 2017**.

End of Support (EoS)

Sunhillo will provide three years support from the EoL (**July 17, 2019**) date after which time Sunhillo will no longer provide any support, nor issue RMAs, for Affected Product. In the event that 3rd party components used in the manufacture of Affected Product are declared EoL or test rigs become unavailable, prior to the EoS date stated in this notice, support will continue to be provided only as may be available to the best of Sunhillo's ability during the remainder of the declared support period for Affected Product.

The following table provides a summary of the lifecycle dates.

Milestone	Date
End of Life (EoL) Date: Date on which Affected Product were declared End of Life	July 18,2016
Last Order Date (LOD): Date after which orders for Affected Product will no longer be accepted by Sunhillo	August 26, 2016
Last Ship Date (LSD): Date after which Affected Product will no longer be shipped from Sunhillo	March 31, 2017
End of Support (EoS) Date: Date after which Affected Product will no longer be supported, nor RMAs issued, by Sunhillo	July 17, 2019

Replacement Product

The replacement for the MPS1000 WAN/LAN Communications Server is the Ventnor Communications Server. The Ventnor platform is designed with the latest technology, ensuring future support and improved performance, and is engineered to be 100% compatible with the existing MPS1000. It utilizes the same MPS Software, and the same Hydra cables, as the MPS1000. The API is unchanged and there should be no reason to change any application that works with a current MPS1000. Ventnor samples will be available in the 3rd quarter 2016 with production scheduled for the 4th quarter 2016.

Further information on this replacement product can be obtained on our website at www.sunhillo.com, or contact Sunhillo Technical support at **+1 856.767.7676**. If you have any questions regarding this notice, please contact your local Sunhillo Sales Representative, who will be happy to help.